
































Инструкция по установке



VN-60









NO.	Designation	Pieces	NO.	Designation	Pieces
1		X1	12		X1
2		X1	13.1		X1
3		X2	13.2		X1
4		X2	14		X2
5		X1	15		X1
6	 $\varnothing 8$	X6+1	16		X2
7	 \oplus ST4X35	X6+1	17		X2
8	 \oplus ST4X10	X4+1	18		X2
9		X4+1	19	1  2 No aluminum 	X2
10	 \oplus ST4X25	X4+1	20	 A.	X2
11.1		X1		 B.1 B.2 B.3 B.4	X4 X4 X2 X2
11.2		X1	 C.1 C.2 C.3 C.4 C.5 C.6	X2 X4 X4 X8 X2 X2	
				 $\varnothing 8$  $\varnothing 3.2$	

1.





	P	W
750	750-800	800
850	850-900	900




2.




3.




4.






5.






e1





6.



7.



8.



9.

24h 

